


FCS-A10



FCS-A10



FCS-A10 installed on Megablock Trunk

- Simple Snap-in installation
- Warns personnel of potential hazard
- Removable and re-usable

The **Megablock Trunk Covers** are designed to provide a reminder to maintenance personnel that care should be exercised before working on the Trunk connectors on the Megablock when it is installed in a hazardous area. The Megablock Trunk Cover is a custom molded plastic piece that is designed to fit on the Megablock Screw Terminal Connectors. It has a yellow warning triangle on its top to provide the warning to personnel. When installed, the screws that are used to secure the Megablock connector to the Megablock, and the screws that fix the wires to the connector are not accessible. To access the screws, the Megablock Trunk Cover must be removed. Once work is complete, it may be re-installed.

A **Typical Use** for the cover is in applications where the Megablock is installed in a Zone 2 or Division 2 hazardous area, and live-working is permitted on the spur connections but not on the trunk. This is the case where the spurs are installed using Ex nL (Europe/IEC practice) or non-incendive field wiring, and connected to suitably certified field devices. The trunk connection must not be live-worked in the presence of the hazardous gasses. The FCS-A10 cover becomes a reminder to take appropriate precautions before maintenance begins.

ORDERING INFORMATION

PART No.	DESCRIPTION
FCS-A10-10	Megablock Trunk Covers (10 pieces)

Note: The Trunk Cover is not designed for Spring Clamp (-PC) connectors.

SPECIFICATIONS

LOCATION OF EQUIPMENT – See specific Megablock Specifications

MOUNTING METHOD – Snaps onto Megablock Connector

MATERIAL – Glass filled Nylon, UL 94V0

ENVIRONMENTAL

Ambient temperature	Operating: -45°C to +70°C Storage: -45°C to +85°C
----------------------------	--

Product Specifications are subject to change without notice.

MECHANICAL DRAWING

